

IECEx Quality Assessment Report Summary

Audit date: 2024-06-04

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **GB/SIR/QAR06.0001/18** Page 1 of 2

QAR Free Ref. No.: 80207899-80207900-80207901-80207902 Status:Issued

Details of change: Recertification Audit Date of issue: 2024-06-21

Location(s) audited: Pyroban Limited Valid until:2027-07-14

Shoreham by Sea West Sussex BN43 6PB

United Kingdom

Issuing ExCB: CSAE - CSA Group Testing UK Ltd

Dolphin Road

Manufacturer: Pyroban Limited

Dolphin Road Shoreham by Sea West Sussex BN43 6PB

Location of Manufacturer:

United Kingdom

Product information: Flame protection, emission controls and gas detection systems: diesel, electric, LPG fork lift trucks, cranes, lifting

equipment, batteres, connectors, solenoids, alternators, interface board.

Type of protection: Ex ia, ib, d, m, e, tb, op is, nA, nC, nR, h Gas Detectors IEC 60079-29, Flame Arrestors ISO 16852

Related QARs:

GB/SIR/QAR06.0001/00 GB/SIR/QAR06.0001/01 GB/SIR/QAR06.0001/02 GB/SIR/QAR06.0001/03 GB/SIR/QAR06.0001/04 GB/SIR/QAR06.0001/05 GB/SIR/QAR06.0001/06 GB/SIR/QAR06.0001/07 GB/SIR/QAR06.0001/08 GB/SIR/QAR06.0001/09 GB/SIR/QAR06.0001/10 GB/SIR/QAR06.0001/11 GB/SIR/QAR06.0001/12 GB/SIR/QAR06.0001/13 GB/SIR/QAR06.0001/14 GB/SIR/QAR06.0001/15 GB/SIR/QAR06.0001/17 GB/SIR/QAR06.0001/16

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx CML 16.0141X issue: 0	IECEx CML 16.0141X issue: 1	IECEx CML 17.0002U issue: 0
IECEx CML 17.0003X issue: 0	IECEx CML 17.0027X issue: 0	IECEx CML 17.0027X issue: 1
IECEx CML 17.0040U issue: 0	IECEx CML 17.0040X issue: 1	IECEx CML 17.0049X issue: 0
IECEx CML 17.0050X issue: 0	IECEx CML 17.0118X issue: 0	IECEx CML 17.0121U issue: 0
IECEx CML 17.0121U issue: 1	IECEx CML 18.0053X issue: 0	IECEx CML 18.0053X issue: 1
IECEx EXV 16.0017X issue: 0	IECEx EXV 16.0017X issue: 1	IECEx EXV 16.0017X issue: 2
IECEx EXV 17.0004 issue: 0	IECEx EXV 17.0004 issue: 1	IECEx EXV 17.0006X issue: 0
IECEx EXV 17.0020U issue: 0	IECEx EXV 20.0055X issue: 0	IECEx EXV 20.0055X issue: 1
IECEx EXV 22.0021X issue: 0	IECEx EXV 22.0022X issue: 0	IECEx ITS 07.0013X issue: 0
IECEx ITS 08.0027X issue: 0	IECEx ITS 08.0027X issue: 1	IECEx ITS 08.0027X issue: 2
IECEx ITS 08.0039X issue: 0	IECEx ITS 09.0004X issue: 0	IECEx ITS 09.0004X issue: 1
IECEx ITS 12.0005X issue: 0	IECEx ITS 12.0005X issue: 1	IECEx ITS 12.0006X issue: 0
IECEx ITS 12.0006X issue: 1	IECEx ITS 12.0006X issue: 2	IECEx ITS 12.0015U issue: 0
IECEx ITS 12.0015U issue: 1	IECEx ITS 13.0008X issue: 0	IECEx ITS 13.0015X issue: 0
IECEx ITS 13.0039X issue: 0	IECEx ITS 13.0039X issue: 1	IECEx ITS 13.0039X issue: 2
IECEx ITS 13.0040X issue: 0	IECEx ITS 14.0038X issue: 0	IECEx ITS 14.0059X issue: 0
IECEx ITS 15.0004 issue: 0	IECEx SEV 16.0001 issue: 0	IECEx SEV 16.0012X issue: 0
IECEx SEV 17.0005 issue: 0	IECEx SEV 17.0005 issue: 1	IECEx SEV 17.0005 issue: 2
IECEx SEV 17.0005 issue: 3	IECEx SEV 17.0019 issue: 0	IECEx SEV 21.0010X issue: 0
IECEx SEV 21.0010X issue: 1 Continued on the next page	IECEx SIR 05.0068X issue: 1	IECEx SIR 05.0068X issue: 2



IECEx Quality Assessment Report Summary

QAR Ref. No.: **GB/SIR/QAR06.0001/18** Page 2 of 2

Related Certificates for previous versions (continued):

IECEx SIR 05.0068X issue: 3 IECEx SIR 06.0088X issue: 0 IECEx SIR 06.0088X issue: 1 IECEx SIR 06.0088X issue: 2 IECEx SIR 06.0088X issue: 3 IECEx SIR 06.0089X issue: 0 IECEx SIR 06.0089X issue: 1 IECEx SIR 06.0089X issue: 2 IECEx SIR 08.0044X issue: 0 IECEx SIR 08.0044X issue: 1 IECEx SIR 09.0048U issue: 0 IECEx SIR 09.0048U issue: 1 IECEx SIR 10.0126X issue: 0 IECEx SIR 10.0126X issue: 1 IECEx SIR 12.0037X issue: 0 IECEx SIR 12.0037X issue: 1 IECEx TRC 15.0009X issue: 0 IECEx TRC 15.0009X issue: 1 IECEx TRC 15.0010X issue: 0 IECEx TRC 15.0010X issue: 1

Comments: Cannock Production Facility (concepts ex d, m, e and t only) - CLOSED 2014